

## Replacement for General Hydraulics Red Green 8 Pin Relay



Replacement\_for\_\_4e29cb88f1f3a.jpg



4049 and 4050 Replacement Red Green Relay for General Hydraulics Balers

Rating: Not Rated Yet

### Price

Sales price \$49.00

Sales price without tax \$49.00

Tax amount

[Ask a question about this product](#)

### Description

Replacment relay for a General Hydraulics Red or Green relay (same Part even though they are different colors) Price is for Each. The custom colored relays as pictured are no longer colored, will be clear. Both Red and Green do the same function and are identical parts even though they were colored and numbered differently by General Hydraulics in the Early 1970's.