

## H-23129 PINION GEAR 15 TOOTH



H\_23129\_PINION\_G\_4ab13844c376d.jpg



H-23129 PINION GEAR 15 TOOTH

Rating: Not Rated Yet

**Price**

Sales price \$273.00

Sales price without tax \$273.00

Tax amount

[Ask a question about this product](#)

Description

This is a 15 Tooth Spline Shaft gear for the motor on American Balers year 2005+. Check your user manual to make sure you are getting the correct gear, you may need part # 500021 instead. The gear pictured here is a 15 tooth gear, some machine use an 18 tooth gear, which is part number 500021