

Turnbuckle RetroFit Kit



Turnbuckle_Retro_4b28e76196fb1.jpg



Baler Turnbuckle Parts Retrofit

Rating: Not Rated Yet

Price

Sales price \$416.16

Sales price without tax \$416.16

Tax amount

[Ask a question about this product](#)

Description

Some Older Vertical Balers Have a Door Opening Mechanism that is no longer OSHA compliant. This New Retrofit includes 2 Steel Mounting Brackets that need to be welded on to the baler and a New Wheel Turnbuckle that holds the door shut.

