

GH Retro-fit kit for obsolete Rotary Valve



General Hydraulics Baler Retro-fit Manifold kit for obsolete (Rotary Valve) actuator -Motor THIS KIT IS NOW OBSOLETE.

Rating: Not Rated Yet

Price

[Ask a question about this product](#)

Description

REC #219010 Four part Retro-fit kit to remove and replace the obsolete actuator(Rotary Valve) motor on the General Hydraulics baler.

***2022 -THIS KIT IS NOW OBSOLETE. GENERAL HYDRAULICS BALERS DO NOT MEET CURRENT SAFETY STANDARDS. PLEASE CAL US TO DISCUSS A MACHINE REPLACEMENT.**